Loading Operating System on TLIN Industrial Computers

The following procedure should be followed when loading a new operating system onto the TLIN industrial computers. These steps need to be performed in the order listed.

1. Load the operating system.

2. Load the mouse driver for your system.

3. Load the Touchscreen driver setting the following parameters.
   A. COM 3
   B. IRQ 11
   C. Address 2E8

4. Load video drivers

The hard drive is partitioned into two separate drives at the factory (C:, D:). The D drive should contain the following directories:

1. Operating system

2. Touchscreen software

3. Video drivers

Technical assistance may be obtained :
In North America EXOR at 1 -513-874-4665.
In Europe EXOR Italy 045 - 8779068